


Libro 101 Costuras - SUMARIO

	CONSTRUCCIÓN	P. 27 C000 COSTURA BÁSICA	C000-1	C000-1 (OS)	C000-1 +SE	P. 30 C100 COSTURA CAÍDA	C100-1	C100-1 +SE	C100-1 (OS)	C100-2	C100-3	C100-3 (OS)	C100-4	
FLAT SEAM	P. 34 C010 COSTURA FRANCESA	C010-1	P. 37 C101 COSTURA RIBETEADA (1)	C101-9	C101-10	C101-12	P. 40 C110 COSTURA PULIDA	C110-1	C110-1x	C110-2	P. 43 C120 COSTURA SOLAPADA	C120-1		
C100-4 (CS)	C100-4 (FS)	P. 46 C200 COSTURA ABIERTA	C200-1	C200-2	C200-2 +SE	C200-1 +SE	C210-3	C201-9	C220-2	P. 50 CD190 COSTURA SÁNDWICH	CD190-1	CD190-2	CD190-4	
C120-4	C120-4 (CS)	P. 57 H000 CANTO PALO SECO	TERMINACIÓN	RAW EDGE	SERGED EDGE	ROLL STITCH EDGE	P. 60 H110 DOBLADILLO DOBLE	H110-2	H110-12	NARROW HEM	ROLL HEM	H100-1 +SE	H100-2 (CS)	
CD190-5	CD190-8	CD190-9												
H100-2 (FS)	H100-0 +BS	H130-3	H130-6	H130-11	H120-1 +SE	H120-2 +SE	H120-3 (CS)	P. 64 H200 CANTO ENVIVADO (1)	H200-1	H200-3 (CS)	P. 67 H101 DOBLAD. RIBETEADO (1)	H101-9	H101-10	
H101-12	P. 70 H150 CANTO CON VISTA	H150-31	H150-32	H150-45x	H140-11 +SE	H140-12 +SE	P. 74 H210 BANDA EXPUESTA	H210-1 +SE	H210-1 (OS)	H210-3	H210-4	H210-4 (CS)	H210-4 (FS)	
H211-9	P. 78 H310 CINTA EXPUESTA	H310-1 (OS)	H310-3	H310-3x	H310-4	H311-9	P. 82 H400 VIVO EXPUESTO	H400-1	H400-2	H400-3	H400-4	H401-9	P. 86 HD190 DOBLADILLO SÁNDWICH	
HD190-1	HD190-2	HD190-4	HD190-5	HD190-8	HD190-10	P. 90 H160 CANTO PLEGADO	H160-0	H160-1	H160-4	DETALLE	P. 97 D210 PARCHE	D210-1	D210-2	
D210-3	D210-4	P. 100 D110 PLIEGUE	D110-0	DART	D110-10	D110-13	D100-1	P. 104 D111 TABLA	D111-0	D111-0A	D111-1	D112-0A	D112-1	D112-5